



Precautionary Measures for Labours Relating to Industry of Stone Cutting, Finishing and Crushing.

Take Precautionary Measures for yourself and your future.


Silicosis is a dangerous disease, which is commonly known as lungs cancer, usually labours relating to this industry does not take precautionary measures and are caused of such dangerous disease like silicosis. Please come and protect yourself and your future by adopting following precautionary measures:

- Display safety sign and safety poster at the working place.
- Water spray must be made by time and again for preventing dust.
- It is necessary to have exit passage for air at the working place.
- It is necessary to use gloves, safety/protective dress and mask.
- Abstain from eating at working place.
- Remove dust from your clothes through vacuum.
- Every labour must be having awareness from life threatening disease like silicoses.

Adopt precautionary measure, save life of your worker and yourself.

Remember: Responsibility rests with you and on us for Saving the Life of worker

For more information please contact on

 **021-99204551**

